


# Personal Protective Equipment

NFPA 70E / CSA Z462 Table Method  
for Equipment Assessment

**e-Hazard**  
Taking the Flash Out of Electrical Safety

(502) 716-7073  
e-Hazard.com



Make Sure Your PPE Meets the **Category Minimum Arc Rating**

✓ **Recommended Best Practice**  
for exposure up to **1.2 cal/cm<sup>2</sup>**



- ✓ Eye Protection
- ✓ Hearing Protection
- Hard Hat
- Face Shield

- ✓ Shirt, long-sleeve & Pants

ALL clothing made of **Non-melting/Natural Fiber**

- Gloves: *Leather, AR, or VR*

- ✓ Leather Footwear



Head

Body

Hands

Feet

● Safety Glasses/Goggles

● Hearing Protection

● Hard Hat

● AR Arc Flash Hood

● or AR Face Shield

● with AR Balaclava for Cat 2

● AR Shirt, long-sleeve & AR Pants

● or AR Coverall

● or AR Arc Flash Suit

● Heavy-duty Leather Gloves

● or AR Gloves

● or Rubber Insulating Gloves with Leather Protectors

● Leather Footwear

○ AR\* Outerwear

\*Only required to meet min. AR if primary protection



- Required
- Required, Choices Available
- As Needed

Requirements per NFPA 70E (2021), Table 130.7(C)(15)(c) / CSA Z462-18, Table 6C